



CIRCUIT BOARD LAYOUT (SOLDER SIDE VIEW)




**TEMPLATE FOR DRILLING HEAT SINKS FOR
OUTPUT TRANSISTORS AND BIAS DIODES**

**THIS LINE MUST MEASURE 6 INCHES! IF IT DOES NOT, YOU HAVE USED THE WRONG
PRINT SETTINGS IN THE ADOBE ADOBE ACROBAT PRINT SETTINGS MENU**



CIRCUIT BOARD LAYOUT (COMPONENT SIDE VIEW)



**TEMPLATE FOR DRILLING HEAT SINKS FOR
OUTPUT TRANSISTORS AND BIAS DIODES**

**THIS LINE MUST MEASURE 6 INCHES! IF IT DOES NOT, YOU HAVE USED THE WRONG
PRINT SETTINGS IN THE ADOBE ADOBE ACROBAT PRINT SETTINGS MENU**